



P.O. Box 249 Tel: (914) 636-1200
 New Rochelle, N.Y. 10802 Fax: (914) 636-1232



BRYN MAWR
PLUMBING AND HEATING

RESIDENTIAL
OIL BURNER CLEAN & TUNE SPECIAL
\$99.00

- *All replacement parts italicized below, and the labor to diagnose, adjust, repair, and/or replace will be covered. *Oil filter element, pump strainer, nozzle, electrodes, cad cell eye w/lead, burner coupling, and nozzle connecting line.*
- *Included in the plan is one (1) scheduled clean & tune of the oil burner.
- *Included in the plan is vacuuming of the heat exchanger, and will be done if needed at time of clean & tune.
- *Included in the plan is vacuuming of the flue pipe, and will be done if needed at time of clean & tune.
- *Included in the plan is cleaning of the chimney base, and will be done if needed at time of clean & tune.
- *Available dates for the clean & tune are between April 15 and October 31.
- *Available hours for the clean & tune are between 8:00 am – 3:00pm, Monday – Friday.
- *No clean & tune appointments will be made during October 31 thru April 15, as our full efforts will be to provide rapid and efficient response to emergency calls, 24 hours a day, 7 days a week.
- *All fuel oil must be purchased from Total Fuel, exclusively. The account must be set up on automatic delivery.
- *An annual fuel minimum of 750 gallons must be purchased to be eligible for the \$99.00 Clean & Tune.
- *Invoices must be paid in full within 10 days from receipt of invoice, unless other arrangements are made before incurring the charges.
- *All labor to diagnose, adjust, repair, and/or replace non-covered parts will be billable at time & materials.
- *A second technician may be needed to perform certain work. When a second technician is needed is the sole decision of Total Fuel. Additional and/or overtime charges may apply, depending on time and date of service.
- *Misuse, abuse, storms, fire, freezing, plugged oil lines, water in fuel tank, multi-fuel units, power outage, obsolete equipment, tripped switches circuit breakers or fuses, flooded boiler, low water in boiler, damage caused by attic fans, defective/improperly set controls, defective/improperly set thermostat, and/or water damage is not covered. All associated diagnosis and/or repairs due to, but not limited to the aforementioned conditions are billable.
- *Coverage of one (1) oil burner per \$99.00 Clean & Tune.

